

NAME Vierra Appliance Sales & Service

MAP NO.: _____

DESCRIPTION South Add. Haysi part of

DISTRICT Haysi Corp

USE		MAIN BUILDING									
<i>Car Wash</i>		CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES		PLUMBING & HEATING			
Dwelling		Wood Frame	Wood Siding	Plaster	Comp. Sh. <input checked="" type="checkbox"/>	Year Built	83	Bathrooms	<i>No</i>		
Store		Steel Frame	Brick	Wall Board	Slate	No. Rooms	3	Basement	<i>No</i>		
Service Station		Tile-C. <i>(Blk)</i>	Asb-wood shing. <input checked="" type="checkbox"/>	Ceiled	Asbestos	No. Stories	1	Fireplace	<i>No</i>		
Garage		Brick	C. Block <input checked="" type="checkbox"/>	Panel	Metal	Foundation		Stoves	<i>No</i>		
Factory		Mill	Stucco	Tile	Tar&Grav.	Floors		Cent. Heat	<i>No</i>		
<i>Car Wash</i>	<input checked="" type="checkbox"/>	Reinf. Conc.		<i>Block</i>	<input checked="" type="checkbox"/>	Porch		Floor Fur.	<i>No</i>		
x 20 x 56 = 1120		CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence		APPRaised VALUE				
		20					\$ <i>22,400 20,000</i>				

OUT BUILDINGS				
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site						<i>50</i>	<i>200</i>	<i>10,000</i>
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes: *DC 7 7415*

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <i>10,000</i>	\$
Bldgs.	\$ <i>22,400 20,000</i>	\$
TOTAL	\$ <i>32,400 20,000</i>	\$

110 Bldg