

NAME Service Station Agnes Fuller

MAP NO.: _____

DESCRIPTION .5385

DISTRICT Sandwich

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh. ✓	Year Built	Bathrooms ✓
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories /	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat ✓
	Reinf. Conc.				Porch	Floor Fur.
$x \quad x \quad =$ $24 \quad 48 \quad = \quad 1152$			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			21	=	=	\$ 24,000 -
			21	=	=	\$ 24,000 -

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site		2000					
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$				

Total Appraised Value All Lands \$

Notes:	RECAPITULATION	
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 2000	\$
Bldgs.	\$ 24000	\$
TOTAL	\$ 26000 -	\$