



Dwelling	Comp. Sh.	Wood Siding	Yr. Built	Remod.	Bsmt. [ ] 2nd [ ]	Plaster	BATH(S) Full 1/2 Bath(s)
Slate		Brick	No. Stories		1st [ ] 3rd [ ]	Sheet rock	Modern Bath [ ] Modern Kitchen [ ]
Asbestos		Asb. Wood Shg.	8. Level [ ] S. Foyer [ ]		Total No. Bedrooms	Ceclled	Cent. Heat [ ] A/C [ ]
Metal		Cin. Block [ ] Stone [ ]				Panel	Fir. or Wall Furnace [ ] Stove(s) [ ]
Wood Frame	Tar & Grav.	Stucco [ ] Con. Block [ ]	Crawl [ ] Conc. [ ]	HW [ ] Pine [ ] Carp. [ ] Tile [ ]	Unfinished		
Cin. Block	Tile	Aluminum [ ] Masonite [ ]	Riers [ ] Cin. Blk. [ ]				Number
Steel Frame	Shakes	Storm Doors [ ] Storm Win. [ ]	Slab [ ] Brick [ ]	Disappearing Stairs	Gd. [ ] Fair [ ] Poor [ ] VP [ ]		Number Chimneys
							Brick [ ] C. Block [ ]
							Stone [ ] Metal [ ]
							YR. 86
							YR.

Porch										
Porch										
Carport										
Garage										
Cent. A/C										
Basement										
Bsmt. Finish										
Attic										
Fireplace(s)										
Heating										
Bath(s)										

Market Value All Improvements	Market Value All Land	5000	5000
Owner <b>LINDA ROSE</b>	Make <b>Richfield</b> Year <b>'74</b>		
Size <b>12 X 65</b> Cond.	Not Home [ ] Time		
APPR. <b>LF</b>	DATE <b>5-9-85</b>		
DATE	CLASSIFICATION	ZONING	
	<b>2</b>		

Land Cost	\$
Bldg. Cost	\$
Sale Price	\$
Rent	\$
Expenses	\$
Net Rent	\$

PROPERTY FACTORS	CLASSIFICATION	ACRES	RATE	ADJ.	CLASSIFICATION	ACRES	RATE	ADJ.
Home Site		1		5000	Home Site			
Wasteland					Wasteland			
U. G. Utilities		1		5000				

General Remarks:

LEVEL [ ] SLOPES UP [ ] SLOPES DOWN [ ]

LOW [ ] STEEP UP [ ] STEEP DOWN [ ]

BOARD REVIEW NOTES