

Dwelling	✓	Comp. Sh.	Wood Siding	Yr. Built 50	Remod.	Bsmt. [] 2nd []	Plaster	BATH(S) Full [] 1/2 Bath(s)
		Slate	Brick	No. Stories 1 1/2	1st 1 1/2 3rd []	Sheet rock	✓	Modern Bath [] Modern Kitchen []
		Asbestos	Asb. Wood Shg.	S. Level [] S. Foyer []	Total No. Bedrooms	Ceciled		Cent. Heat ELEC AC
		Metal	Cin. Block [] Stone []			Panel	✓	Fir. or Wall Furnace [] Stove(s) []
Wood Frame	✓	Tar & Grav.	Stucco [] Con. Block []	Crawl [] Conc. []	HW [] Pine [] Carp. [] Tile []	Unfinished		
Cin. Block		Tile	Aluminum [] Masonite []	Riers [] Cin. Bk. []				
Steel Frame		Shakes	Storm Doors [] Storm Win. []	Slab [] Brick []	Disappearing Stairs	Gd. [] Fair [] Poor [] VP []		Number

1 1/2 SFR 180627.5 49665

Dwelling				D		50642	4000	30385
Porch	144	8	1152				FV	800
Porch								
Carport	330	6	1980					
Garage								
Cent. A/C								
Basement	602	65	3913					
Bsmt. Finish								
Attic								
Fireplace(s)			1500					
Heating								
Bath(s)								
Total			58210					
Factor			.87					
Replacement			50642					

M & L	M & L	Market Value All Improvements	54500
DATE	DATE	Market Value All Land	10400
APRP.	APRP.	TOTAL MARKET VALUE	64900
DATE	DATE		
CLASSIFICATION	ZONING		

Public Water	✓	Paved	✓	Home Site	10.60	600	4000	6360
Public Sewer		Gravel						
Well		Dirt						
Spring		No Road						
Septic System	✓	Curb & Gutter						
U. G. Utilities		Sidewalk						

LEVEL [] SLOPES UP [] SLOPES DOWN []	General Remarks: value set on garage set much too high last time.
LOW [] STEEP UP [] STEEP DOWN []	

BOARD REVIEW NOTES