

To the best of my knowledge the
Dorchester ~~team~~ underlies about 45 acres
of the 60-acre surface tract described in
D.B. 45, P. 189. Of the 45 acres, 10 acres was mined
by Leonard E. Mullins under lease from W.M. Phipps
and others in the 1950, and I would estimate that
35 acres of Dorchester coal remains.

Present ownership of the mineral rights to
the tract is as follows.

J. C. Buchanan	$\frac{1}{10}$ by heirship
" "	$\frac{5}{10}$ by purchase from F. L. Buchanan & Stella Buchanan (Deed dated 10th day of Nov, 1956 and not yet recorded — but will be recorded right away)
N. J. Buchanan	$\frac{1}{10}$ by heirship.
"	$\frac{1}{10}$ by purchase from heirs of W. B. Willis (?)
Heirs of W. M. Phipps	$\frac{2}{10}$

Please Complete One of These Forms for Each Seam on Each Tract, Both Fee Simple Tracts and Mineral Rights Tracts.

Buchanan, John C. Name of Owner of Mineral

Mineral Only

WISE, VA.

Lessor (if applicable)

Fee Simple

NAME OF COAL SEAM

DORCHESTER

{owns only
36. in all
12.
6.
6.
6.

Pound River

Ident. of tract & No. Acres

1/2 of 60 acres (more or less) of

List names of owners of

surface owned, I believe

Surface and App. No. of

by Logan Childress. This

acres owned by each one

is the tract, excepted by

(use back of this form if

Willis in sale of land, DC 45

more space is needed)

(see other side)

Coal Bearing Area

Outcrop (that cannot be stripped or augered)

From a

Recoverable Coal

Survey by Mr. Runyon

REPORT FOR YEAR 1997

of the area mined by

Recoverable Coal

Leonard Mullins, this seems

Depleted During 19

to be about the average of

Depleted Prior to 19

the Dorchester seam

Not Movable (Please list reasons-Rolls, etc)

To Remain Unmined (Reservations, etc.)

Lost Coal (List reason such as "squeeze" etc.)

Deductions to December 31, 19

Remaining Recoverable Coal

No. Acres	Avg. Hgt.	Tons Removed
	Coal 6"	
	slate 7"	
	Coal 21"	
	slate 5"	
	Coal 4"	

Please list names of all mines that are operating in this seam now or did operate during 19

I do hereby certify that the above information to be true and correct to the best of my knowledge and belief.

John C. Buchanan Engineer

Ownership of minerals under
the surface described in D.B. 45, P189:

J.C. Buchanan $\frac{6}{10}$

N.J. Buchanan $\frac{2}{10}$

Heirs of W.M. Phipps $\frac{2}{10}$.

Dickenson County

District

Please Complete One of These Forms for Each Seam on Each Tract, Both Fee Simple Tracts and Mineral Rights Tracts.

Name of Owner of Mineral

[] Mineral Only

Lessor (if applicable)

[] Fee Simple

NAME OF COAL SEAM

CLINTWOOD

Ident. of tract & No. Acres

List names of owners of

Surface and App. No. of

acres owned by each one

(use back of this form if

more space is needed)

So far as I know, no survey of clintwood seam has been made, but I have been told by coal men that perhaps 20 or 3 acres of the boacre surface tract is underlain by this seam.

Coal Bearing Area	No. Acres	Avg. Hgt.	Tons Removed
Outcrop (that cannot be stripped or sugered)			
Recoverable Coal			
Recoverable Coal			
Depleted During 19			
Depleted Prior to 19			
Not Movable (Please list reasons-Rolls, etc)			
To Remain Unmined (Reservations, etc.)			
Lost Coal (List reason such as "squeeze" etc.)			
Deductions to December 31, 19			
Remaining Recoverable Coal			

REPORT FOR YEAR 19

(OVER)

Please list names of all mines that are operating in this seam now or did operate during 19

I do hereby certify that the above information to be true and correct to the best of my knowledge and belief.

Signature: [Handwritten Signature] Engineer