



NAME Viers, Billy & MARY  
Hackney, Johnny M. & Tenaris

MAP NO.: \_\_\_\_\_

DESCRIPTION Laurel Branch 0.9

DISTRICT Sandlick

**MAIN BUILDING**

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.		=	=
						APPRAISED VALUE
						\$

**OUT BUILDINGS**

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

**LAND**

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site							
2. Residential							
3. Agricultural	0.9	FV	300				
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
<b>TOTAL</b>	0.9		\$				

Total Appraised Value All Lands \$

Notes:

	RECAPITULATION	
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 300	\$
Bldgs.	\$	\$
<b>TOTAL</b>	\$	\$