

Dwelling	Comp. Sh.	Wood Siding	Yr. Built	Remod.	Bemt. [] 2nd []	Plaster	BATH(S) Full 1/2 Bath(s)
	Slate	Brick	No. Stories		1st [] 3rd []	Sheet rock	Modern Bath [] Modern Kitchen []
	Asbestos	Asb. Wood Shg.	S. Level [] S. Foyer []		Total No. Bedrooms	Ceciled	Cent. Heat [] A/C []
	Metal	Cin. Block [] Stone []				Panel	Fir. or Wall Furnace [] Stove(s) []
Wood Frame	Tar & Grav.	Stucco [] Con. Block []	Crawl [] Conc. []	HW [] Pine [] Carp. [] Tile []		Unfinished	
Cin. Block	Tile	Aluminum [] Masonite []	Riers [] Cin. Blk. []				
Steel Frame	Shakes	Storm Doors [] Storm Win. []	Slab [] Brick []	Disappearing Stairs		Gd. [] Fair [] Poor [] VP []	Number
			Basement Size	Attic Floor & Stairs			Number Chimneys
			Gd. [] Fair [] Poor [] VP []	Basmt. Finish	1/4 [] 1/2 [] 3/4 [] Full []	Attic [] Walls [] Fl. []	Brick [] C. Block []
						YR. <u>86</u>	Stone [] Metal []

Porch									
Porch									
Carport									
Garage									
Cent. A/C									
Basement									

Bemt. Finish	M & L	M & L	DATE	DATE	APRP.	APRP.	DATE	DATE	CLASSIFICATION	ZONING	OWNER	Market Value All Improvements	Market Value All Land
Attic													
Fireplace(s)													
Heating													
Bath(s)													
Total													
Factor													
Replacement													

Land Cost													
Bldg. Cost													
Sale Price													
Rent													
Expenses													
Net Rent													

PROPERTY FACTORS		CLASSIFICATION	ACRES	RATE	ADJ.	CLASSIFICATION	ACRES	RATE	ADJ.
Public Water	Paved	Home Site	1			Home Site		1000	
Public Sewer	Gravel								
Well	Dirt								
Spring	No Road								
Septic System	Curb & Gutter	Wasteland				Wasteland			
U. G. Utilities	Sidewalk		1					1000	

General Remarks: Topo Poor
Poor Access to Water

LEVEL SLOPES UP SLOPES DOWN
 LOW STEEP UP STEEP DOWN

BOARD REVIEW NOTES