

NAME Moore, Radford & Louise

MAP NO.: _____

X

DESCRIPTION Yates Gap 2 trs. 2.50

DISTRICT Clintwood

2

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING	
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms ✓	
Store	Steel Frame	Brick ✓	Wall Board ✓	Slate	No. Rooms 5	Basement ✓	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace	
Garage	Brick	C. Block	Panel	Metal ✓	Foundation	Stoves ✓	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat HA.	
	Reinf. Conc.				Porch	Floor Fur.	
X	X	=	CU. FT. SQ. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
					=	=	FV \$ 6500

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1	FV	4000					
2. Residential								
3. Agricultural	1/2	FV	7000.50					
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$ 4700.50					

Total Appraised Value All Lands \$

Notes: no age recorded

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 4500	\$
Bldgs.	\$ 6500	\$
TOTAL	\$ 11000	\$