

NAME Mullins, Edna

MAP NO.: _____

DESCRIPTION Grand View Add. .25

DISTRICT Clintwood

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.		=	=
						APPRaised VALUE
						FV \$16,200 + 14,000

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House	F.	F.	3,000	FV 3,000 2,000 + 1,000
Misc. Bldg.				

Total Appraised Value All Improvements \$19,200 + 13,000

LAND

	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1/4	FV	3,500	3				
2. Residential				1,000.00				
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes:	RECAPITULATION	
	APPRAISED VALUE	ASSESSED VALUE
Land	\$	\$ 1,000.00
Bldgs.	\$	\$ 13,000
TOTAL	\$	\$ 14,000