



NAME Mullins, James Carl & Deloras

MAP NO.: \_\_\_\_\_

DESCRIPTION Bartley Branch 5.13

DISTRICT Sandlick Clintwood

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING	
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms	
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace	
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	
	Reinf. Conc.				Porch	Floor Fur.	
X	X	=	CU. FT. SQ. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE
				=	=	=	\$

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	1	FV	3000				
2. Residential							
3. Agricultural	4.13	54300	<del>200</del> 1200				
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$ 510 4200				

Total Appraised Value All Lands \$

Notes: \_\_\_\_\_

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 510 4200	\$
Bldgs.	\$	\$
TOTAL	\$ 510 4200	\$