

NAME Mullins, James E.

MAP NO.: _____

DESCRIPTION Cutter Creek .41

DISTRICT Clintwood

MAIN BUILDING										
USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING				
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms				
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms 4	Basement				
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace				
Garage	Brick	C. Block	Panel	Metal	Foundation 5	Stoves				
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat				
	Reinf. Conc.				Porch	Floor Fur.				
X 24 x 24 = 576			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE			
			SQ. FT.		=	=	\$ 7000 7000			

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.	3	frame only		3	200

Total Appraised Value All Improvements \$ ~~7000~~ 7000

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site			1200					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes:	RECAPITULATION	
	APPRAISED VALUE	ASSESSED VALUE
	Land \$ 1200	\$
	Bldgs. \$ 7300	\$
	TOTAL \$ 8500	\$