

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

DESCR. Billy Green

SUBD.

FRONT FEET.

LOT

一、测试目的

ACREAGE 12

[illegible]

17: Donnie Joe Mullins 88144.232

DESCRIPTION Nelly Creek

DISTRICT Glendale

BLOCK _____

HOUSE NO. _____

MAIN BUILDING

USE		CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEAT	
Dwelling	✓	Wood Frame		Wood Siding		Plaster	✓	Comp. Sh.	✓	Year Built		Bathrooms	
Store		Steel Frame		Brick	✓	Wall Board		Slate		No. Rooms	4	Basement	
Service Station		Tile-C. Bk		Asb-wood shing.		Ceiled		Asbestos		No. Stories	1 1/2	Fireplace	
Garage		Brick	✓	C. Block		Panel		Metal		Foundation	S	Stoves	
Factory		Mill		Stucco		Tile		Tar&Grav.		Floors	H	Cent. Heat	HN
		Reinf. Conc.								Porch	✓	Floor Fur.	
X		X	=	CU. FT.		UNIT FACTOR		TOTAL		Physical Depreciation or Obsolescence		APPRaised VAL	
				SQ. FT.				=		-		\$	

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				
Store 1	✓ CB		Small	
Total Appraised Value All Improvements \$ <u>14,400</u>				

LAND

USE	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appr. Seed V
1. Tillable								
2. Pasture								
3. Timber								
4. Out Over								
5. Marsh - Mountain								
6. Commerical								
7. Industrial								
8. Mineral								
TOTALS	<u>2.</u>	<u>0</u>	\$ <u>900</u>					

Total Appraised Value All Lands \$

Notes:

BUILDING PERMITS

No.	Type	Date	% of Comp	Plat A.

RECAPITULATION

Bldgs.	APPRAISED VALUE	ASSESSED
	<u>14,400</u>	<u>1,440</u>
	<u>900</u>	<u>90</u>
TOTAL	<u>15,300</u>	<u>1,530</u>