

NAME Mullins, Jerry & Veneda

MAP NO.: _____

X

DESCRIPTION Cutter Branch 1.

DISTRICT Clintwood

USE	MAIN BUILDING											
	CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING	
Dwelling <input checked="" type="checkbox"/>	Wood Frame <input checked="" type="checkbox"/>		Wood Siding <input checked="" type="checkbox"/>		Plaster		Comp. Sh. <input checked="" type="checkbox"/>		Year Built		Bathrooms <input checked="" type="checkbox"/>	
Store	Steel Frame		Brick		Wall Board		Slate		No. Rooms	5	Basement	
Service Station	Tile-C. Blk		Asb-wood shing.		Ceiled		Asbestos		No. Stories	1	Fireplace	
Garage	Brick		C. Block		Panel <input checked="" type="checkbox"/>		Metal		Foundation	<input checked="" type="checkbox"/>	Stoves	
Factory	Mill		Stucco		Tile		Tar&Grav.		Floors		Cent. Heat	<input checked="" type="checkbox"/>
	Reinf. Conc.								Porch	<input checked="" type="checkbox"/>	Floor Fur.	
X	X	=			CU. FT.	UNIT FACTOR	TOTAL		Physical Depreciation or Obsolescence		APPRAISED VALUE	

USE	CONSTRUCTION	CONDITION	OUT BUILDINGS	SIZE	GEN. REMARKS	APPRAISED VALUE
Garage						
Barn						
Chicken House						
Tenant House		new		24 x 50 =	1200 x 100	20,400 ✓
Misc. Bldg.	Metal & wood					800 ✓
						300 ✓

Total Appraised Value All Improvements \$ ~~13600~~ 11100

LAND

	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1							
2. Residential			3000					
3. Agricultural			1500					
4. Commercial			1000					
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL								

Total Appraised Value All Lands \$

Notes: _____

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 1500 <u>1100</u>	\$
Bldgs.	\$ 11100	\$
TOTAL	\$ 12600 <u>12200</u>	\$