

NAME Mullins, Jimmy R. & Buford Jimmy R

MAP NO.: _____

DESCRIPTION Georges Fork 1.50

DISTRICT Clintwood

MAIN BUILDING									
USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING			
Dwelling	<input checked="" type="checkbox"/> Wood Frame	<input checked="" type="checkbox"/> Wood Siding	<input checked="" type="checkbox"/> Plaster	Comp. Sh.	Year Built	Bathrooms	<i>No</i>		
Store	Steel Frame	Brick	Wall Board	<input checked="" type="checkbox"/> Slate	No. Rooms	Basement	<i>No</i>		
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace			
Garage	Brick	C. Block	Panel	Metal	<input checked="" type="checkbox"/> Foundation	Stoves	<input checked="" type="checkbox"/>		
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat			
	Reinf. Conc.				Porch	Floor Fur.			
X	X	=	CU. FT. SQ. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE		
					=	=	<i>R</i> \$ <i>4000</i> <i>2000</i>		

OUT BUILDINGS				
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.	<i>2 Frame</i>			<i>R</i> <i>300</i>

ABOVE HOUSE IS IN POOR CONDITION

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	<i>1 1/2</i>	<i>R</i>	<i>3000</i> <i>2000</i>					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes: *No Bldg*

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <i>2000</i>	\$ <i>2000</i>
Bldgs.	\$ <i>4300</i>	\$ <i>2000</i>
TOTAL	\$ <i>6300</i>	\$ <i>4000</i>