

NAME Mullins, Johnny C.

MAP NO.: _____

DESCRIPTION Pound River 0.98

DISTRICT Clintwood

MAIN BUILDING

2

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES		PLUMBING & HEATING	
					Year Built	No. Rooms	Bathrooms	Basement
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	6/10	Bathrooms	2
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	6	Basement	NO
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	1	Fireplace	1
Garage	Brick	C. Block	Panel	Metal	Foundation	5	Stoves	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors		Cent. Heat	elect BB
	Reinf. Conc.				Porch		Floor Fur.	
$x \ 30 \times 64 = 1920 \text{ @ } 22 \text{ CU. FT.}$ SQ. FT.				UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE	
				=	=	=	\$ 42200 38400	

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

Lots

	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1.07	3700	4000					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes:

1st Union Church

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 3000	\$
Bldgs.	\$ 38400	\$
TOTAL	\$ 41400	\$