

20/45

NAME Mullins, Mary Britton

MAP NO.: _____

7

DESCRIPTION Camp Creek 19.75

DISTRICT Clintwood
VH 1/10/80 2

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms <i>No</i>
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms <i>6</i>	Basement <i>No</i>
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories <i>1</i>	Fireplace
Garage	Brick	C. Block	Panel	Metal ✓	Foundation	Stoves <i>Gas</i>
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.	<i>Alum</i>	<i>unfin.</i>		Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.		=	=
						FV \$ 3000 2000

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House	✓ Log Tiv P...	One Room		FV 500
Misc. Bldg.				

Total Appraised Value All Improvements \$ ~~3500~~ 2500

LAND

	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1	FV	4000 1000					
2. Residential								
3. Agricultural	18.3	500	9150					
4. Commercial		300						
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$ 13800 1000					

Total Appraised Value All Lands \$

Notes:

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 6600	\$
Bldgs.	\$ 2500	\$
TOTAL	\$ 9100	\$