

NAME Mullins, Woodrow & Vivian

MAP NO.: _____

x

DESCRIPTION Long Branch 1.

DISTRICT Clintwood

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms 1
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms 7	Basement <i>1/2 Not Finish.</i>
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace 1
Garage	Brick	C. Block	Panel	✓ Metal	Foundation 5	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat <i>C.F. H.A.</i>
	Reinf. Conc.				Porch	Floor Fur.

$35\frac{1}{2} \times 38$ 7×31	$24\frac{1}{2} \times 7 = 1737$	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE
		SQ. FT.	20	=	=	35800 30000

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.	2 Fr			FU 200

Total Appraised Value All Improvements \$ ~~36000~~ 30200

LAND

	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1	FV	5000	4000				
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes:	RECAPITULATION		
		APPRAISED VALUE	ASSESSED VALUE
	Land	\$ 4000	\$
	Bldgs.	\$ 30200 32400	\$
	TOTAL	\$ 34200 36400	\$