

NAME Vanover, Esta & ETALS

MAP NO.: _____

X

DESCRIPTION Osborne Gap School 0.50

DISTRICT Clintwood

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING	
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms	
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace	
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	
	Reinf. Conc.				Porch	Floor Fur.	
X	X	=	CU. FT. SQ. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
				=	=		\$

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.	<i>Detached Bldg.</i>			<i>RV 1000</i>

Total Appraised Value All Improvements \$

LAND

Lots

	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	<i>1/2</i>	<i>12</i>	<i>1500</i>					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes:	RECAPITULATION	
	APPRAISED VALUE	ASSESSED VALUE
	Land \$ <i>1500</i>	\$
	Bldgs. \$ <i>1000</i>	\$
	TOTAL \$ <i>2500</i>	\$