

BENNETT MARTELINA
 BOX 212
 MUYSI VA 24256

DATE RECORDED 12-5-85
 DEED OR WILL BOOK W/B 17 568
 CONSIDERATION

CLASS 1
 ZONING
 DISTRICT 07
 LEGAL DESCRIPTION
 MCCLURE CITY
 LOT 3
 BLOCK 4

DATE RECORDED
 DEED OR WILL BOOK
 CONSIDERATION

1992	2000	20800	22800
1993	2000	20800	22800
1994			
1995			


DATE RECORDED
 DEED OR WILL BOOK
 CONSIDERATION

1996			
1997			
1998			
1999			

DATE RECORDED
 DEED OR WILL BOOK
 CONSIDERATION

2000			
2001			
2002			
2003			

DATE RECORDED
 DEED OR WILL BOOK
 CONSIDERATION



NOTES:

Dwelling	<input checked="" type="checkbox"/>	Comp. Sh.	Wood Siding	Yr. Built	Remod.	Basmt. [] 2nd []	Plaster	BATH(S) Full 1/2 Bath(s)
		Slate	Brick	No. Stories		1st (4) 3rd []	Sheet rock	Modern Bath <input type="checkbox"/> Modern Kitchen <input type="checkbox"/>
		Asbestos	Asb. Wood Shg.	S. Level <input type="checkbox"/> S. Foyer <input type="checkbox"/>		Total No. Bedrooms	Ceiled	Cent. Heat Oil AC
		Metal	Cin. Block <input type="checkbox"/> Stone <input type="checkbox"/>				Panel	Flr. or Wall Furnace <input type="checkbox"/> Stove
Wood Frame	<input checked="" type="checkbox"/>	Tar & Grav.	Stucco <input type="checkbox"/> Con. Block <input type="checkbox"/>	Crawl <input type="checkbox"/> Conc. <input type="checkbox"/>		100 <input type="checkbox"/> Pine <input type="checkbox"/> Carp. <input type="checkbox"/> Tile <input type="checkbox"/>	Unfinished	Number 10
Cin. Block		Tile	Aluminum <input checked="" type="checkbox"/> Masonite <input type="checkbox"/>	Fiers <input type="checkbox"/> Cin. Blk <input checked="" type="checkbox"/>				Number Chimneys
Steel Frame		Shakes	Storm Doors <input type="checkbox"/> Storm Win. <input type="checkbox"/>	Slab <input type="checkbox"/> Brick <input type="checkbox"/>		Disappearing Stairs	Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>	Brick [] C. Block []
				Basement Size 10		Attic Floor & Stairs		Stone [] Metal []
				Basmt. Finish		1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full <input type="checkbox"/>	Attic <input type="checkbox"/> Wells <input type="checkbox"/> Fl. <input type="checkbox"/>	YR. 91

15 R 976 30 29280

Dwelling				DT	87732	25%	80799
Porch	144	6	864				
Porch							
Garport							
Garage							
Cent. A/C							

Basement	M & L	M & L	Market Value All Improvements	20800
Basmt. Finish	DATE	DATE	Market Value All Land	2000
Attic	APRP	APRP.	Owner	22800
Hearth(s)	DATE 8/21/91	DATE	Make	
Heating			Size	
Bath(s)			Not Home <input type="checkbox"/> Time	
Total	30144		AM <input type="checkbox"/> PM <input type="checkbox"/>	
Factor	.98		CLASSIFICATION	ZONING
Replacement	27732		1	

Land Cost	
Bldg. Cost	
Sale Price	
Rent	
Expenses	
Net Rent	

25

80 8000

Public Water	<input checked="" type="checkbox"/>	Paved	<input checked="" type="checkbox"/>	CLASSIFICATION	ACRES	RATE	ADJ.	CLASSIFICATION	ACRES	RATE	ADJ.
Public Sewer	<input checked="" type="checkbox"/>	Gravel		Home Site				Home Site			
Well		Dirt									
Spring		No Road									
Septic System		Curb & Gutter		Wasteland				Wasteland			
U. S. Utilities		Sidewalk									

General Remarks:

LEVEL SLOPE UP SLOPE DOWN
 LOW STEEP UP STEEP DOWN

BOARD REVIEW NOTES