

MULLINS ANDREW J & LOIS  
RT 1 BOX 1  
HAYSI VA


24256

DATE RECORDED 5-75  
DEED OR WILL BOOK DB 0171 0438  
CONSIDERATION

CLASS 1  
ZONING  
DISTRICT 07

LEGAL DESCRIPTION  
HAYSI  
LOT 16  
BLOCK 4

1992				
1993				
1994	2,000	24,100	26,100	
1995	2,000	24,100	26,100	
1996				
1997				
1998	2,000	24,100	26,100	
1999				
2000				
2001				
2002				
2003				



NOTES:

Dwelling	<input checked="" type="checkbox"/>	Comp. Sh.	<input checked="" type="checkbox"/>	Wood Siding		Yr. Built 78	Remod.		Bemt. ( ) 2nd ( )	Plaster		BATH(S) 2 Full 1/2 Bath(s)
		Slate		Brick		No. Stories	1		1st ( ) 3rd ( )	Sheet rock	<input checked="" type="checkbox"/>	Modern Bath <input type="checkbox"/> Modern Kitchen <input type="checkbox"/>
		Asbestos		Asb. Wood Shg.		S. Level <input type="checkbox"/> S. Foyer <input type="checkbox"/>			Total No. Bedrooms	Ceiled		Cent. Heat elec AC
		Metal		Cin. Block <input type="checkbox"/> Stone <input type="checkbox"/>						Panel	<input checked="" type="checkbox"/>	Fir. or Wall Furnace <input type="checkbox"/> Stove(s) <input type="checkbox"/>
Wood Frame	<input checked="" type="checkbox"/>	Tar & Grav.		Stucco <input type="checkbox"/> Con. Block <input type="checkbox"/>		Crawl <input type="checkbox"/> Conc. <input type="checkbox"/>			HW <input type="checkbox"/> Pine <input type="checkbox"/> Carp. <input type="checkbox"/> Tile <input type="checkbox"/>	Unfinished		
Cin. Block		Tile		Aluminum <input checked="" type="checkbox"/> Masonite <input type="checkbox"/>		Floors <input type="checkbox"/> Cin. Blk. <input type="checkbox"/>						Number NO
Steel Frame		Shakes		Storm Doors <input type="checkbox"/> Storm Win. <input type="checkbox"/>		Slab <input type="checkbox"/> Brick <input type="checkbox"/>			Disappearing Stairs		Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>	Number Chimneys

Basement Size	NO	Attic Floor & Stairs		Brick ( ) C. Block ( )
Basmt. Finish		1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full <input type="checkbox"/>		Stone ( ) Metal ( )
Gd. <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>		Attic <input type="checkbox"/> Walls <input type="checkbox"/> Fl. <input type="checkbox"/>		

1STy 1364 22 30008

Dwelling					28111	15%	23894
Porch	0	288	8	2304			
Porch							
Carport							
Garage							
Cent. A/C							

1STy FR Utility 14x16

FV 200

Basement	M & L	M & L	Market Value All Improvements	24100
Basmt. Finish	DATE	DATE	Market Value All Land	2000
Attic	APPR. DR	APPR.	Owner	26100
Fireplace(s)	DATE 3-14-94	DATE	Make	
Heating	CLASSIFICATION	ZONING	Size	
Bath(s)			Not Home <input type="checkbox"/> Time	
Total			Agric.	
Factor			Hort.	
Replacement			Forest	
			Open Space	
			Totals	

Land Cost	\$
Bldg. Cost	\$
Sale Price	\$
Rent	\$
Expenses	\$
Net Rent	\$

Public Water	<input checked="" type="checkbox"/> Paved	<input checked="" type="checkbox"/>	Home Site		Home Site	
Public Sewer	<input checked="" type="checkbox"/> Gravel					
Well	Dirt					
Spring	No Road					
Septic System	Curb & Gutter	Wasteland		Wasteland		
U. G. Utilities	Sidewalk					2000

General Remarks:

LEVEL  SLOPES UP  SLOPES DOWN

LOW  STEEP UP  STEEP DOWN

BOARD REVIEW NOTES