

NAME Mullins, BLUFORD + Queenie MARY

MAP NO.:

DESCRIPTION 0.23 CHASE Hollow

DISTRICT Town of Whitwood

MAIN BUILDING

USE	CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING	GENERAL FEATURES		PLUMBING & HEATING	
								Year Built		Bathrooms	
Dwelling	Wood Frame		Wood Siding		Plaster		Comp. Sh.		No. Rooms		Basement
Store	Steel Frame		Brick		Wall Board		Slate		No. Stories		Fireplace
Service Station	Tile-C. Blk		Asb-wood shing.		Ceiled		Asbestos		Foundation		Stoves
Garage	Brick		C. Block		Panel		Metal		Floors		Cent. Heat
Factory	Mill		Stucco		Tile		Tar & Grav.		Porch		Floor Fur.
	Reinf. Conc.										
			CU. FT.		UNIT FACTOR		TOTAL		Physical Depreciation or Obsolescence		APPRAISED VALUE
X	X	=					=	=			\$
			SQ. FT.								

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				
Total Appraised Value All Improvements				\$

LAND

	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site								
2. Residential	.23	F.V.	2,500					
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$	Total Appraised Value All Lands				\$

RECAPITULATION

Notes:	APPRAISED VALUE	ASSESSED VALUE
	Land \$ 2,500.00	\$
	Bldgs. \$	\$
	TOTAL \$	\$