



DESCRIPTION CRACKED BRICK

DISTRICT SANDLICK

**MAIN BUILDING**

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	✓ Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
$X \quad X \quad =$ $28 \quad 54 \quad = \quad 1512$			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.			APPRaised VALUE
						\$

**OUT BUILDINGS**

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	APPRaised VALUE
Garage	2 <u>used</u>			<u>Incomplete</u>	<u>20,000</u>
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$

**LAND**

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site							
2. Residential							
3. Agricultural	<u>7.1417</u>	<u>F.V.</u>	<u>2500.00</u>				
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
<b>TOTAL</b>			\$				

Total Appraised Value All Lands \$

Notes: DEED 213-326 CALLS FOR 7.1417  
NO ADVERSE GIVEN

**RECAPITULATION**

	APPRaised VALUE	ASSESSED VALUE
Land	\$ <u>2,500.00</u>	\$
Bldgs.	\$ <u>20,000</u>	\$
<b>TOTAL</b>	\$ <u>22,500</u>	\$