

NAME Danny N. & Barbara A. Mullins

MAP NO.: _____

DESCRIPTION TARPOON

DISTRICT SANDLICK

1973 ^{10/10/84}

MAIN BUILDING										
USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING				
Dwelling <u>MH</u>	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms				
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement				
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace				
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves				
Factory	Mill	Stucco	Tile	Tar & Grav.	Floors	Cent. Heat				<u>oil</u>
	Reinf. Conc.				Porch	Floor Fur.				

<u>12</u> x <u>55</u> x _____ = _____	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
<u>696</u> <u>80</u> FT. @ <u>12</u>			<u>= 8400 + = 400</u>		<u>\$ 8800</u>

PORCH 6x12 = 72 @ 6 = 430

USE/roof	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ _____

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	<u>1</u>	<u>1000</u>	<u>1000</u>					
2. Residential								
3. Agricultural	<u>1</u>	<u>300</u>	<u>300</u>					
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$ _____					

Total Appraised Value All Lands \$ 1300

Notes: MH on this property
off Hwy 83 - left. Behind R+GMA

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <u>1300</u>	\$ <u>1300</u>
Bldgs.	\$ <u>8800</u>	\$ <u>8800</u>
TOTAL	\$ <u>10100</u>	\$ <u>10100</u>