

NAME Stanley, Draxie S.

MAP NO.: _____

x

DESCRIPTION McClure Lot 47

DISTRICT Ervinton

MAIN BUILDING <i>Nh-11:30 2/27/79</i>													
USE	CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING		
Dwelling	<input checked="" type="checkbox"/>	Wood Frame	<input checked="" type="checkbox"/>	Wood Siding	<input checked="" type="checkbox"/>	Plaster		Comp. Sh.	<input checked="" type="checkbox"/>	Year Built		Bathrooms	
Store		Steel Frame		Brick		Wall Board	<input checked="" type="checkbox"/>	Slate		No. Rooms	4	Basement	SINK
Service Station		Tile-C. Blk		Asb-wood shing.		Ceiled	<input checked="" type="checkbox"/>	Asbestos		No. Stories		Fireplace	
Garage		Brick		C. Block		Panel		Metal		Foundation		Stoves	
Factory		Mill		Stucco		Tile		Tar&Grav.		Floors		Cent. Heat	
		Reinf. Conc.								Porch		Floor Fur.	
x		x		=		CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence		APPRAISED VALUE		
						SQ. FT.		=	=		FV \$ 5000		

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	<i>Lot</i>	<i>FV</i>	<i>3000 / 1500</i>					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes:	RECAPITULATION		
		APPRAISED VALUE	ASSESSED VALUE
	Land	\$ <i>5000 1500</i>	\$
	Bldgs.	\$ <i>3000</i>	\$
	TOTAL	\$ <i>8000 4500</i>	\$