

| | | |
|---|-------------------|-----------------|
| PYXIS RESOURCES CO C/O ED STACY P O BOX 4000 LEBANON VA 24266 | DATE RECORDED | 12-9-92 |
| | DEED OR WILL BOOK | DB 0288 0084 |
| | CONSIDERATION | 175,000.00 |
| | DATE RECORDED | |
| | DEED OR WILL BOOK | |
| | CONSIDERATION | |
| | DATE RECORDED | |
| | DEED OR WILL BOOK | |
| | CONSIDERATION | |
| | DATE RECORDED | |
| | DEED OR WILL BOOK | |
| | CONSIDERATION | |
| | DATE RECORDED | |
| | DEED OR WILL BOOK | |
| | CONSIDERATION | |


| | | |
|----------|----|--|
| CLASS | 4 | LEGAL DESCRIPTION FRYING PAN 56.6337 AC 178-148A (A) 1624 |
| ZONING | | |
| DISTRICT | 02 | |

| | | | |
|------|--------|-------|--------|
| 1992 | | | |
| 1993 | | | |
| 1994 | 18,700 | 6,400 | 25,100 |
| 1995 | 18,700 | 6,400 | 25,100 |
| 1996 | | | |
| 1997 | | | |
| 1998 | | | |
| 1999 | | | |
| 2000 | | | |
| 2001 | | | |
| 2002 | | | |
| 2003 | | | |

BUILDING PERMITS

| NO. | TYPE | DATE | REMARKS |
|-----|------|------|---------|
| | | | |
| | | | |
| | | | |
| | | | |

NOTES: 287-418 Release of interest O Duane
 Sutherland Land Etals 11-13-92
 decrease changed by survey made by
 Lemmon Landside for Brenda Kelgore 1-2-93



| | | | | | | | |
|-------------|-------------------------------------|---|--|---|---|--|---|
| Dwelling | <input checked="" type="checkbox"/> | Comp. Sh. | Wood Siding | Yr. Built <u>25</u> Remod. | Bemt. [] 2nd [] | Plaster | BATHS / Full 1/2 Bath(s) |
| | | Slate | Brick | No. Stories <u>1</u> | 1st <u>5</u> 3rd [] | Sheet rock | Modern Bath <input type="checkbox"/> Modern Kitchen <input type="checkbox"/> |
| | | Asbestos | Asb. Wood Shg. | S. Level <input type="checkbox"/> S. Porch <input type="checkbox"/> | Total No. Bedrooms | Ceciled | Cent. Heat <u>COA1</u> A/C |
| | | Metal <input checked="" type="checkbox"/> | Cin. Block <input type="checkbox"/> Stone <input type="checkbox"/> | | | Panel | Fir. or Wall Furnace <input type="checkbox"/> Stove(s) <input type="checkbox"/> |
| Wood Frame | <input checked="" type="checkbox"/> | Tar & Grav. | Stucco <input type="checkbox"/> Con. Block <input type="checkbox"/> | Crwl <input type="checkbox"/> Conc. <input type="checkbox"/> | HW <input type="checkbox"/> Pine <input type="checkbox"/> Carp. <input type="checkbox"/> Tile <input checked="" type="checkbox"/> | Unfinished | |
| Cin. Block | | Tile | Aluminum <input checked="" type="checkbox"/> Masonite <input type="checkbox"/> | Flrs <input type="checkbox"/> Cin. Blk. <input checked="" type="checkbox"/> | | | Number |
| Steel Frame | | Shakes | Storm Doors <input type="checkbox"/> Storm Win. <input type="checkbox"/> | Slab <input type="checkbox"/> Brick <input type="checkbox"/> | Disappearing Stairs | Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/> | Number Chimneys |
| | | | Basement Size <u>NO</u> | Attic Floor & Stairs | | | Brick [] C. Block [] |
| | | | Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/> | Basmt. Finish | 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full <input type="checkbox"/> | Attic <input type="checkbox"/> Walls <input type="checkbox"/> Fl. <input type="checkbox"/> | Stone [] Metal [] |

PFR 744 31 23,064

| | | | | | | | | | | | |
|-----------|------------|----------|----------|--|----------|---------------|------------|-------------|--|--|--|
| | | | Dwelling | | <u>2</u> | <u>18,270</u> | <u>652</u> | <u>6394</u> | | | |
| Porch | <u>216</u> | <u>6</u> | | | | | | | | | |
| Porch | | | | | | | | | | | |
| Carport | | | | | | | | | | | |
| Garage | | | | | | | | | | | |
| Cent. A/C | | | | | | | | | | | |

| | | | | |
|---------------|----------------|-------|--|---------------|
| Basement | M & L | M & L | Market Value All Improvements | <u>6400</u> |
| Basmt. Finish | DATE | DATE | Market Value All Land | <u>18700</u> |
| Attic | APRP. | APRP. | Owner | <u>25,100</u> |
| Fireplace(s) | <u>m.s.</u> | | Make | Year |
| Heating | DATE | DATE | Size | Cond. |
| Bath(s) | <u>1-31-94</u> | | Not Home <input type="checkbox"/> Time | |
| Total | <u>24,360</u> | | AM <input checked="" type="checkbox"/> PM <input type="checkbox"/> | |
| Factor | <u>75</u> | | Agric. | |
| Replacement | <u>18,270</u> | | Hort. | |
| | | | Forest | |
| | | | Open Space | |
| | | | Totals | |

| | | | | | | | |
|-----------------|--------------|--------------|---------------|----------------|-------|---------------|------|
| CLASSIFICATION | ACRES | RATE | ADJ. | CLASSIFICATION | ACRES | RATE | ADJ. |
| Home Site | <u>1</u> | | | Home Site | | | |
| Public Water | <u>Woods</u> | <u>55.63</u> | <u>2000</u> | | | <u>16,690</u> | |
| Public Sewer | | | | | | | |
| Well | | | | | | | |
| Spring | | | | | | | |
| Septic System | | | | | | | |
| U. G. Utilities | | <u>56.63</u> | <u>18,700</u> | | | | |

General Remarks: Topo V. Poor

SLOPES UP SLOPES DOWN
 LOW STEEP UP STEEP DOWN

BOARD REVIEW NOTES