



|  |   |  |  |  |  |  |  |
|--|---|--|--|--|--|--|--|
| Dwelling <input checked="" type="checkbox"/>   | Comp. Sh. <input checked="" type="checkbox"/> | Wood Siding <input checked="" type="checkbox"/>                          | Yr. Built <u>40</u>  | Remqd. <input type="checkbox"/>  | Bemt. [ ] 2nd [ ]  | Plaster <input type="checkbox"/>   | BATH(S) Full <input type="checkbox"/> 1/2 Bath(s) <input type="checkbox"/> |
|  | Slate <input type="checkbox"/>                | Brick <input type="checkbox"/>   | No. Stories <u>1</u>   | 1st <u>5</u> 3rd [ ]   | Sheet rock <input checked="" type="checkbox"/>   | Modern Bath <input type="checkbox"/> Modern Kitchen <input type="checkbox"/>               |  |
|  | Asbestos <input type="checkbox"/>             | Asb. Wood Shg. <input type="checkbox"/>                                  | S. Level <input type="checkbox"/> S. Foyer <input type="checkbox"/>          | Total No. Bedrooms <u>1</u>  | Ceciled <input type="checkbox"/>   | Cent. Heat <u>WOOD</u> A/C <u>NO</u>   |  |
|  | Metal <input checked="" type="checkbox"/>     | Cin. Block <input type="checkbox"/> Stone <input type="checkbox"/>       |  |  | Panel <input type="checkbox"/>   | Fir. or Wall Furnace <input type="checkbox"/> Stove(s) <input checked="" type="checkbox"/> |  |
| Wood Frame <input checked="" type="checkbox"/> | Tar & Grav. <input type="checkbox"/>          | Stucco <input type="checkbox"/> Con. Block <input type="checkbox"/>      | Crawl <input type="checkbox"/> Conc. <input type="checkbox"/>                | HW <input type="checkbox"/> Pine <input checked="" type="checkbox"/> Carp. <input type="checkbox"/> Tile <input checked="" type="checkbox"/> | Unfinished <input type="checkbox"/>  | Number <u>NO</u>   |  |
| Cin. Block <input type="checkbox"/>            | Tile <input type="checkbox"/>                 | Aluminum <input type="checkbox"/> Masonite <input type="checkbox"/>      | Riers <input type="checkbox"/> Cin. Blk. <input checked="" type="checkbox"/> |  |  | Number Chimneys <u>NO</u>  |  |
| Steel Frame <input type="checkbox"/>           | Shakes <input type="checkbox"/>               | Storm Doors <input type="checkbox"/> Storm Win. <input type="checkbox"/> | Slab <input type="checkbox"/> Brick <input type="checkbox"/>                 | Disappearing Stairs <input type="checkbox"/>   | Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/> | Brick [ ] C. Block [ ]   |  |

|      |     |      |       |  |                         |                      |                         |  |                     |                 |     |     |
|------|-----|------|-------|--|-------------------------|----------------------|-------------------------|--|---------------------|-----------------|-----|-----|
| 1sty | 930 | 29.5 | 27435 | Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/> | Basmt. Finish <u>NO</u> | Attic Floor & Stairs | Basmt. Finish <u>NO</u> | Attic <input type="checkbox"/> Walls <input type="checkbox"/> Fl. <input type="checkbox"/> | Stone [ ] Metal [ ] | YR. <u>1994</u> | YR. | YR. |
|------|-----|------|-------|--|-------------------------|----------------------|-------------------------|--|---------------------|-----------------|-----|-----|

|           |     |             |      |  |         |                       |      |                    |       |
|-----------|-----|-------------|------|--|---------|-----------------------|------|--------------------|-------|
| Dwelling  | E-  | 20654 - 759 | 5163 | Market Value All Improvements                                      | 6400    | Market Value All Land | 7200 | TOTAL MARKET VALUE | 13600 |
| Porch     | 276 | 6           | 1656 | Owner  |         | Make                  | Year | Size               | Cond. |
| Porch     |     |             |      | Not Home <input checked="" type="checkbox"/> Time                  |         | Agric.                |      | Hort.              |       |
| Carport   |     |             |      | AM <input type="checkbox"/> PM <input checked="" type="checkbox"/> |         | Forest                |      | Open Space         |       |
| Garage    |     |             |      | Land Cost  |         | Totals                |      | Bldg. Cost         |       |
| Cent. A/C |     |             |      | DATE   | 2-17-94 | Expenses              |      | Net Rent           |       |

paved Dwy  
FR misc  
BIK cellar 8x10

} FV 1000  
} FV 200

|             |       |      |         |                |   |        |  |
|-------------|-------|------|---------|----------------|---|--------|--|
| Total       | 29091 | DATE | 2-17-94 | CLASSIFICATION | 2 | ZONING |  |
| Factor      | .71   |      |         |                |   |        |  |
| Replacement | 20654 |      |         |                |   |        |  |

|                 |               |                |           |       |      |      |                |           |       |      |      |
|-----------------|---------------|----------------|-----------|-------|------|------|----------------|-----------|-------|------|------|
| Public Water    | Paved         | CLASSIFICATION | Home Site | ACRES | RATE | ADJ. | CLASSIFICATION | Home Site | ACRES | RATE | ADJ. |
| Public Sewer    | Gravel        |                | Hillside  | 1.    |      |      |                |           |       |      |      |
| Well            | Dirt          |                | topo/poor | 14.   | 300  |      |                |           |       |      |      |
| Spring          | No Road       |                |           |       |      |      |                |           |       |      |      |
| Septic System   | Curb & Gutter |                | Wasteland |       |      |      | Wasteland      |           |       |      |      |
| U. G. UTILITIES | Sidewalk      |                |           | 15'   |      |      |                |           |       |      |      |

General Remarks:

LEVEL  SLOPES UP  SLOPES DOWN

LOW  STEEP UP  STEEP DOWN

BOARD REVIEW NOTES