



NAME Belcher, Clynard & Wife

MAP NO.: \_\_\_\_\_

DESCRIPTION Little Prater Gap 1.

DISTRICT Sandlick

2

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING		GENERAL FEATURES		PLUMBING & HEATING	
				Comp. Sh.	Year Built	No. Rooms	Bathrooms		
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	No. Rooms	Bathrooms	Basement	
Store	Steel Frame	Brick	Wall Board	Slate		No. Stories		Fireplace	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos		Foundation		Stoves	
Garage	Brick	C. Block	Panel	Metal		Floors		Cent. Heat	
Factory	Mill	Stucco	Tile	Tar&Grav.		Porch		Floor Fur.	
	Reinf. Conc.								

$7 \times 16 + 42 \times 40 = 1792$

CU. FT.  
SQ. FT.

UNIT FACTOR

TOTAL

Physical Depreciation  
or Obsolescence

APPRAISED VALUE

26 24

~~\$ 48100~~ 44500

OUT BUILDINGS

*OR 7x20 + 7x24 = 308 @ 5. = 1540*

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	1	F.V.	5000				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
<b>TOTAL</b>			\$				

Total Appraised Value All Lands \$

Notes:

*Handwritten notes on top of top...*

RECAPITULATION

APPRAISED VALUE

ASSESSED VALUE

Land

\$ 5000 5000

Bldgs.

\$ 48100 44500

TOTAL

\$ 53100 49500