

NAME Haga, Michael V. + Marilyn B.

MAP NO.: _____

OK

DESCRIPTION Bartley Branch 1.08

DISTRICT Clintwood

MAIN BUILDING													
USE	CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING		
Dwelling	<input checked="" type="checkbox"/>	Wood Frame	<input checked="" type="checkbox"/>	Wood Siding		Plaster		Comp. Sh.		Year Built	80	Bathrooms	2
Store		Steel Frame		Brick		Wall Board		Slate		No. Rooms	6	Basement	In C.P.
Service Station		Tile-C. Blk		Asb-wood shing.		Ceiled		Asbestos		No. Stories	1	Fireplace	
Garage		Brick		C. Block		Panel	<input checked="" type="checkbox"/>	Metal		Foundation	Bl.	Stoves	
Factory		Mill		Stucco		Tile		Tar&Grav.		Floors		Cent. Heat	Elect.
		Reinf. Conc.		<u>Alum. S.</u>	<input checked="" type="checkbox"/>					Porch		Floor Fur.	
X	X	=		CU. FT.		UNIT FACTOR		TOTAL		Physical Depreciation or Obsolescence		APPRAISED VALUE	
				SQ. FT.									\$ 20,000.00

OUT BUILDINGS				
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site								
2. Residential	1-A	11	3000.					
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL	1.08		\$ 5000.00					

Total Appraised Value All Lands \$ 500.00

Notes: Basement Incomplete

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 500.00	\$ 3000.
Bldgs.	\$ 20000.00	\$ 20000.
TOTAL	\$ 20500.00	\$ 23000.