

NAME Garton, Carlos D.

MAP NO.: _____

X

DESCRIPTION Lazarus Branch 1.70

DISTRICT Sandlick

MAIN BUILDING *NH-1.15 8/21/77*

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING	
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms 1	
Store	Steel Frame	Brick <i>Siding</i> ✓	Wall Board ✓	Slate	No. Rooms 6	Basement <i>117</i>	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace	
Garage	Brick	C. Block	Panel	Metal ✓	Foundation	Stoves ✓	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	
	Reinf. Conc.				Porch	Floor Fur.	
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE
			SQ. FT.		=	=	FY \$ <i>6000 3000</i>

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.	<i>FR</i>			<i>FR 200</i>

Total Appraised Value All Improvements \$ *6200 3200*

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	<i>1.7</i>	<i>FV</i>	<i>3200/1200</i>				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$				

Total Appraised Value All Lands \$

Notes: *See House Inventory - 11/1/77*

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <i>3200 1200</i>	\$
Bldgs.	\$ <i>6000 3000</i>	\$
TOTAL	\$ <i>9200 4200</i>	\$