

Haysi Community Clinic inc

NAME Mullins, Willie & Joyce

DESCRIPTION Bartlick Creek 1.50

MAP NO.: _____

DISTRICT ~~VILLE~~ Landlick

BLOCK _____ HOUSE NO. _____

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEAT
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh. ✓	Year Built <u>70</u>	Bathrooms ✓
Store	Steel Frame	Brick ✓	Wall Board ✓	Slate	No. Rooms <u>5</u>	Basement <u>NO</u>
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories <u>1</u>	Fireplace
Garage	Brick	C. Block	Panel ✓	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat ✓
	Reinf. Conc.				Porch	Floor Fur.
30 x 50 x =			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			1500 SQ. FT.	8/10	=	APPRAISED VALUE
						\$15,000 1.50

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage <u>Car port</u>				
Barn ✓				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 15,000

LAND

USE	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appra
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS	1.50		1000 \$1,000					

Total Appraised Value All Lands \$ _____

Notes Well Water good

BUILDING PERMITS

No.	Type	Date	% of Comp	Final A.

RECAPITULATION

	APPRAISED VALUE	ASSESSED VA
Land	\$ 1000	\$ 100
Bldgs.	\$ 15100	\$ 1510
TOTAL	\$ 16100	\$ 1610

