

NAME Hill, Frank & Bertha
 DESCRIPTION Bartlick 1.

MAP NO.: _____
 DISTRICT Sandlick

BLOCK _____ HOUSE NO. _____

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh. ✓	Year Built	Bathrooms ✓
Store	Steel Frame	Brick	Wall Board ✓	Slate	No. Rooms 5	Basement ✓
Service Station	File-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace
Garage	Brick	C. Block	Panel ✓	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch ✓	Floor Fur. <u>Ein</u>
30 x 36 x = 1080 CU. FT.			UNIT FACTOR 6.04	TOTAL =	Physical Depreciation or Obsolescence	APPRAISED VALUE \$ 6,480

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage ✓	CB	P	2 Car	
Barn				100
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 6,580

LAND

USE	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraisal
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS	1.		\$ 400					

Total Appraised Value All Lands \$ 400

Notes: _____

BUILDING PERMITS

No.	Type	Date	% of Comp	Final A.

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 400	\$ 40
Bldgs.	\$ 6,580	\$ 6,600
TOTAL	\$ 6,980	\$ 6,640

