

NAME Lyall, Vaughn

MAP NO. _____

DESCRIPTION Tom Bottom 0.75

DISTRICT Willis Sandlick

BLOCK _____

HOUSE NO. _____

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEAT
Dwelling	<input checked="" type="checkbox"/> Wood Frame	<input checked="" type="checkbox"/> Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.		<i>Paper</i>	<i>Comp</i>	Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.			APPRaised VALU
						\$ 400 800

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House	<i>1</i>	<i>1</i>	<i>3000</i>	
Misc. Bldg.				<i>100</i>

Total Appraised Value All Improvements \$ 900

LAND

USE	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appra
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS	<i>0.75</i>		<i>400</i> <i>\$ 200</i>					

Total Appraised Value All Lands \$ 400

Notes: Valley Sandlick Hall
3rd house

BUILDING PERMITS

No.	Type	Date	% of Comp	Final A.

RECAPITULATION

	APPRAISED VALUE	ASSESSED VA
Land	\$ <u>400</u>	\$ <u>40</u>
Bldgs.	\$ <u>900</u>	\$ <u>90</u>
TOTAL	\$ <u>1300</u>	\$ <u>130</u>

