

NAME Mullins, Angeline *SEP Rufus*

MAP NO.: _____

DESCRIPTION Bartlick Creek 2.

DISTRICT Sandlick

MAIN BUILDING												
USE	CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING	
Dwelling	<input checked="" type="checkbox"/>	Wood Frame	<input checked="" type="checkbox"/>	Wood Siding		Plaster		Comp. Sh.		Year Built		Bathrooms
Store		Steel Frame		Brick <i>Comp</i>		Wall Board	<input checked="" type="checkbox"/>	Slate		No. Rooms	5	Basement
Service Station		Tile-C. Blk		Asb-wood shing.		Ceiled		Asbestos		No. Stories	1	Fireplace
Garage		Brick		C. Block		Panel		Metal	<input checked="" type="checkbox"/>	Foundation	5	Stoves
Factory		Mill		Stucco		Tile		Tar&Grav.		Floors		Cent. Heat
		Reinf. Conc.								Porch		Floor Fur.
X	X	=		CU. FT.		UNIT FACTOR		TOTAL		Physical Depreciation or Obsolescence		APPRAISED VALUE
				SG. FT.				=		=		F.V. \$ 500

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.	<input checked="" type="checkbox"/>	<i>C15</i>			F.V. 500

Total Appraised Value All Improvements \$ 5500

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	<i>1.5775</i>	<i>FV</i>	<i>4000 3000</i>					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes: *Fig. 2 returned*

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <i>4000 3000</i>	\$
Bldgs.	\$ <i>5500</i>	\$
TOTAL	\$ <i>9500</i>	\$