

NAME Mullins, Aughtha

MAP NO.: _____

DESCRIPTION Bartlick l.

DISTRICT Sandlick

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES		PLUMBING & HEATING	
					Year Built	No. Rooms	Bathrooms	Basement
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	✓ Comp. Sh.	Year Built	No. Rooms 4	Bathrooms 1/2	Basement
Store	Steel Frame	Brick	Wall Board	Slate	No. Stories		Fireplace	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	Foundation		Stoves	✓
Garage	Brick	C. Block	Panel	Metal	Floors		Cent. Heat	
Factory	Mill	Stucco	Tile	Tar&Grav.	Porch	1	Floor Fur.	
	Reinf. Conc.	<i>Masonry</i> ✓			Physical Depreciation or Obsolescence		APPRaised VALUE	
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	=	=	\$ 5,000.00
			SQ. FT.					

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				
Total Appraised Value All Improvements				\$

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	1 A.	40000	400.00				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$ 40000				
Total Appraised Value All Lands				\$			

RECAPITULATION

Notes:	APPRAISED VALUE	ASSESSED VALUE
	Land \$ 400.00	\$
	Bldgs. \$ 5,000.00	\$
	TOTAL \$ 5,400.00	\$