

NAME Mullins, Bonnie  
Turner, J E & Wife

MAP NO.: \_\_\_\_\_

DESCRIPTION Lazarus Branch 20-11-62

DISTRICT Sandlick

BLOCK \_\_\_\_\_ HOUSE NO. \_\_\_\_\_

**MAIN BUILDING**

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING	
Dwelling	Wood Frame ✓	Wood Siding ✓	Plaster	Comp. Sh.	Year Built	Bathrooms ✓	
Store	Steel Frame	Brick siding ✓	Wall Board ✓	Slate	No. Rooms 4	Basement NO	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace	
Garage	Brick	C. Block	Panel	Metal ✓	Foundation P	Stoves ✓	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors P	Cent. Heat	
	Reinf. Conc.				Porch ✓	Floor Fur.	
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE
			SQ. FT.		=		\$ 1000 12.00

**OUT BUILDINGS**

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 1200

**LAND**

USE	No. Acres	Value Per Acre	TOTAL	Lots				Appraised Value
				Lot No.	Zoning	Size	Front Ft. Factor	
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS	11.62	40	\$ 600					

Total Appraised Value All Lands \$

Notes:

*Le from Virgil Turner  
op side Bab*

**BUILDING PERMITS**

No.	Type	Date	% of Comp	Final A.

**RECAPITULATION**

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 600	\$ 80
Bldgs.	\$ 1200	\$ 120
TOTAL	\$ 1800	\$ 180

