

MULLINS BUSTER & MARILYN
RT 1 BOX 389
HAYSI VA

24256

DATE RECORDED 7-76
DEED OR WILL BOOK DB 0178 0218
CONSIDERATION


CLASS 2
ZONING
DISTRICT 04
LEGAL DESCRIPTION
BARTLICK
.25AC

1992			
1993			
1994	3,500	20,200	23,700
1995	3,500	20,200	23,700
1996	3500	20,200	23,700
1997	3500	20,200	23,700
1998	3500	22600	24,100
1999			
2000			
2001			
2002			
2003			

BUILDING PERMITS

NO.	TYPE	ISS.	ISSUED	EXPIRES	STATUS

NOTES:



Dwelling	<input checked="" type="checkbox"/>	Comp. Sh.	<input checked="" type="checkbox"/>	Wood Siding		Yr. Built 90 Remod.		Bemt. [] 2nd []	Plaster		BATH(S) \$ 500
		Slate		Brick		No. Stories	1	1st [5] 3rd []	Sheet rock		Modern Bath <input type="checkbox"/> (Water Heating) <input type="checkbox"/>
		Asbestos		Asb. Wood Shg.		S. Level <input type="checkbox"/> S. Foyer <input type="checkbox"/>		Total No. Bedrooms	Ceciled		Cent. Heat <input checked="" type="checkbox"/> (Water) <input type="checkbox"/> NO
		Metal		Cln. Block <input type="checkbox"/> Stone <input type="checkbox"/>					Panel	<input checked="" type="checkbox"/>	Fir. or Wall Furnace <input type="checkbox"/> Stove(s) <input type="checkbox"/>
Wood Frame	<input checked="" type="checkbox"/>	Tar & Grav.		Stucco <input type="checkbox"/> Con. Block <input type="checkbox"/>		Crawl <input type="checkbox"/> Conc. <input type="checkbox"/>		HW <input type="checkbox"/> Pine <input type="checkbox"/> Carp. <input type="checkbox"/> Tile <input checked="" type="checkbox"/>	Unfinished		
Cln. Block		Tile		Aluminum <input checked="" type="checkbox"/> Masonite <input type="checkbox"/>		Riers <input type="checkbox"/> Cln. Blk. <input checked="" type="checkbox"/>					Number NO
Steel Frame		Shakes		Storm Doors <input type="checkbox"/> Storm Win. <input type="checkbox"/>		Slab <input type="checkbox"/> Brick <input type="checkbox"/>		Disappearing Stairs			Number Chimneys

1st 918 31.5 28917				Gd. <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>	Basement Size NO	Attic Floor & Stairs		Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>	Basmt. Finish	1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full <input type="checkbox"/>	Attic <input type="checkbox"/> Walls <input type="checkbox"/> Fl. <input type="checkbox"/>	Stone <input type="checkbox"/> Metal <input type="checkbox"/>
--------------------	--	--	--	---	------------------	----------------------	--	--	---------------	--	--	---

											YR. 1994	YR.	YR.
--	--	--	--	--	--	--	--	--	--	--	----------	-----	-----

Dwelling						D		24449	1886	20048		
Porch	90	6	540									
Porch												
Carport												
Garage												
Cent. A/C												
Basement												
Basmt. Finish												
Attic												
Fireplace(s)												
Heating												
Bath(s)												
Total			29457									
Factor			.83									
Replacement			24449									

M & L	M & L	Market Value All Improvements	20300	22100
DATE	DATE	Market Value All Land	3500	3500
APRP. HB	APRP. BA	TOTAL MARKET VALUE	23700	26100
DATE 2-24-94	DATE 1-14-98			
CLASSIFICATION 2	ZONING			

Owner	Make	Year	Size	Cond.	Not Home <input checked="" type="checkbox"/> Time	Agric.	Hort.	Forest	Open Space	Totals	Land Cost	\$
					AM <input type="checkbox"/> PM <input checked="" type="checkbox"/>						Bldg. Cost	\$

Frontage	Depth	Square Footage	Lot Price	Front Footage	Front Ft. Price	TOTAL	Lot Price	Depth	Front Ft. Price	TOTAL	Lot Price	Depth	TOTAL

PROPERTY FACTORS		CLASSIFICATION	ACRES	RATE	ADJ.	CLASSIFICATION	ACRES	RATE	ADJ.
Public Water	Paved	Home Site				Home Site			
Public Sewer	Gravel		.25					3500	
Well	Dirt								
Spring	No Road <input checked="" type="checkbox"/>								
Septic System	Curb & Gutter	Wasteland				Wasteland			
U. G. Utilities	Sidewalk		.25					3500	

General Remarks:

LEVEL SLOPES UP SLOPES DOWN

LOW STEEP UP STEEP DOWN

BOARD REVIEW NOTES