

NAME Mullins, Ida & Husband

MAP NO.: _____

x

DESCRIPTION Big Ridge 5.

DISTRICT Sandlick

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.			APPRaised VALUE
						F.V. \$ 6000 5000

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House	✓ 1st fl. room	Used for storage	5 V.	500 V.I.
Misc. Bldg.				

Total Appraised Value All Improvements \$ 6500

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	2	250 FA	5000				
2. Residential							
3. Agricultural	3	500 300	1500 900				
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$ 6500				

Total Appraised Value All Lands \$

Notes: 1 of 723 trails on property.

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 6500 11.777	\$
Bldgs.	\$ 1500 5000	\$
TOTAL	\$ 8000	\$