



NAME Mullins, James W. & Wife

MAP NO.: \_\_\_\_\_

x

DESCRIPTION Prater Creek .50

DISTRICT Sandlick

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING	
Dwelling	✓ Wood Frame	✓ Wood Siding	✓ Plaster	Comp. Sh.	✓ Year Built	Bathrooms	
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms 4	Basement	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace	
Garage	Brick	C. Block	Panel	✓ Metal	Foundation 5	Stoves	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	
	Reinf. Conc.				Porch	Floor Fur.	
X	X	=	CU. FT. SQ. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE
				=	=		EV \$ 5000

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	1/2	EV	2000				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$				

Total Appraised Value All Lands \$

Notes: Lf 83W Blue Rd.

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 2000	\$
Bldgs.	\$ 5000	\$
TOTAL	\$	\$