



NAME Mullins, John H. & Inis

MAP NO.: \_\_\_\_\_

DESCRIPTION Low Gap Branch 1.7

DISTRICT Sandlick

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
10' x 45' <i>mobile Home</i> x 450'		CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
		SQ. FT.		=	=	\$ 2500

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.	FR			FV 200
Rooms to let	2 rms, Alum sh		8x44 + 22x4 = 440 sq @ 8	FI 3500
Total Appraised Value All Improvements \$ 3700				

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	1.75	FV	4500 3000				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$				
Total Appraised Value All Lands \$							

Notes: *R 3/ 33*

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 4500 <i>3000</i>	\$
Bldgs.	\$ 3700 <i>6200</i>	\$
TOTAL	\$ 8200 <i>9200</i>	\$