

Dwelling	Comp. Sh. <input checked="" type="checkbox"/>	Wood Siding	Yr. Built <u>85</u>	Remod.	Bsmt. <input type="checkbox"/> 2nd <input type="checkbox"/>	Plaster	BATH(s) <input checked="" type="checkbox"/> Full <input type="checkbox"/> 1/2 Bath(s)
<u>Store</u>	<input checked="" type="checkbox"/> Slate	Brick	No. Stories <u>1</u>		1st <input type="checkbox"/> 3rd <input type="checkbox"/>	Sheet rock	Modern Bath <input type="checkbox"/> Modern Kitchen <input type="checkbox"/>
	Asbestos	Asb. Wood Shg.	S. Level <input type="checkbox"/> S. Foyer <input type="checkbox"/>		Total No. Bedrooms	Ceiled	Cent. Heat <input type="checkbox"/> A/C <input type="checkbox"/>
	Metal	Cin. Block <input type="checkbox"/> Stone <input type="checkbox"/>				Panel	Fir. or Wall Furnace <input type="checkbox"/> Stove(s) <input checked="" type="checkbox"/>
Wood Frame <input checked="" type="checkbox"/>	Tar & Grav.	Stucco <input type="checkbox"/> Con. Block <input type="checkbox"/>	Crawl <input type="checkbox"/> Conc. <input type="checkbox"/>	HW <input type="checkbox"/> Pine <input type="checkbox"/> Carp. <input type="checkbox"/> Tile <input type="checkbox"/>	Unfinished		Number
Cin. Block	Tile	Aluminum <input checked="" type="checkbox"/> Masonite <input type="checkbox"/>	Fiers <input type="checkbox"/> Cin. Blk. <input type="checkbox"/>				Number Chimneys
Steel Frame	Shakes	Storm Doors <input type="checkbox"/> Storm Win. <input type="checkbox"/>	Slab <input type="checkbox"/> Brick <input type="checkbox"/>	Disappearing Stairs		Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input checked="" type="checkbox"/>	Brick <input type="checkbox"/> C. Block <input type="checkbox"/>
		Basement Size <u>FULL</u>	Attic Floor & Stairs				Stone <input type="checkbox"/> Metal <input type="checkbox"/>
		Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>	Bsmt. Finish	1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full <input type="checkbox"/>	Attic <input type="checkbox"/> Walls <input type="checkbox"/> Fl. <input type="checkbox"/>	YR. <u>94</u>	YR.

Porch									
Porch									
Carport									
Garage									
Cent. A/C									
Basement									
Bsmt. Finish									
Attic									
Fireplace(s)									
Heating									
Bath(s)									
Total									
Factor									
Replacement									

Market

2/3/95 FV 11000
1000

1000

M & L	M & L	Market Value All Improvements	4000
DATE	DATE	Market Value All Land	2500
APRP <u>mc</u>	APRP.		6500 3500
DATE <u>2/24/94</u>	DATE		
CLASSIFICATION <u>4</u>	ZONING		

Public Water	Paved								
Public Sewer	Gravel								
Well	Dirt								
Spring	No Road								
Septic System	Curb & Gutter	Wasteland							
U. G. Utilities	Sidewalk								

CLASSIFICATION	ACRES	RATE	ADJ.	CLASSIFICATION	ACRES	RATE	ADJ.
Home Site	<u>.12</u>			Home Site		<u>2500</u>	
				Wasteland		<u>2500</u>	

General Remarks: *Bldg. rained in 5-3-89 and found to be in a very depreciated state. 2/3/95 Bldg. had been totally vandalized and city in order*

LEVEL SLOPES UP SLOPES DOWN

LOW STEEP UP STEEP DOWN

BOARD REVIEW NOTES