

NAME Mullins, Martin & Gladys

MAP NO.: _____

x

DESCRIPTION Bartlick Creek 1.

DISTRICT Sandlick

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	✓ Plaster	Comp. Sh.	Year Built	Bathrooms <i>No</i>
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms <i>?</i>	Basement <i>No</i>
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	✓ Metal	✓ Foundation	Stoves <i>2</i>
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
$X \quad X \quad =$			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.		=	=
						APPRaised VALUE
						<i>FV. \$ 2500</i>

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site <i>H</i>	<i>1</i>	<i>FV</i>	<i>2000/1500</i>				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$				

Total Appraised Value All Lands \$

Notes: *P 2/6/11*

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <i>2000</i>	\$
Bldgs.	\$ <i>2500</i>	\$
TOTAL	\$ <i>4500</i>	\$