

NAME Mullins, Ruey K + Linda A.  
Mullins, Jimmy & Linda

MAP NO.: \_\_\_\_\_  
 DISTRICT IN 1110 Sandlick

DESCRIPTION Grassy Creek Lot 100x85

BLOCK \_\_\_\_\_ HOUSE NO. \_\_\_\_\_

**MAIN BUILDING**

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING	
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms	
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace	
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves	
Factory	Mill	Stucco	Tile	Tar & Grav.	Floors	Cent. Heat	
	Reinf. Conc.				Porch	Floor Fur.	
X	X	=	CU. FT. SQ. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
					=	-	<del>2000</del> 2500

**OUT BUILDINGS**

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 2500

**LAND**

USE	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commerical								
7. Industrial								
8. Mineral								
TOTALS	0.25		400 \$ 200					

Total Appraised Value All Lands \$ 400

Notes: Behind Herb Steiner + Ring Mullins

BUILDING PERMITS					
No.	Type	Date	% of Comp	Final A.	

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 400	\$ 40
Bldgs.	\$ 2500	\$ 250
TOTAL	\$ 2900	\$ 290

