

NAME Mullins, Tivia & Beasia

DESCRIPTION Grassy Cr. lot 56x260

MAP NO.: _____

DISTRICT ~~11111~~ San Diego

BLOCK _____ HOUSE NO. _____

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEAT
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Ash-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.			APPRaised VALU

4500 1800

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 1800

LAND

USE	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appra
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS	<u>Lot</u>		<u>600</u>					

Total Appraised Value All Lands \$ _____

Notes: Asst.

BUILDING PERMITS

No.	Type	Date	% of Comp	Final A.

RECAPITULATION

	APPRAISED VALUE	ASSESSED VA
Land	\$ <u>600</u>	\$ <u>600</u>
Bldgs.	\$ <u>1800</u>	\$ <u>1800</u>
TOTAL	\$ <u>2400</u>	\$ <u>2400</u>

7545

MAP NO. _____

RECORD OF OWNERSHIP

DB. PG. DATE CONSIDERATION

Mullins, Tivis & Bessie
 Box 1016
 Grandy, Va. 24614
 c/o T. C. Mullins

DESCR. Grassy Creek

SUBD. _____

LOT _____ BLOCK _____ SECTION _____

ACREAGE Lot 56x260

YEAR	VALUE OF LAND	VALUE OF IMPROVEMENTS	TOTAL VALUE	TAX RATE	TOT. LEV.
73	60	180	240		16.8
74	60	180	240		17.8
75	60	180	240		18.0
76	60	180	240		20.1
77	60	180	240		24.0
78	60	180	240		25.2
79	60	180	240		25.2

REMARKS