

NAME Mullins, William Ervin & Wife

MAP NO.: _____

DESCRIPTION Mill Creek 5.

DISTRICT Sandlick 1

BLOCK _____ HOUSE NO. _____

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEAT
Dwelling	✓ Wood Frame	✓ Wood Siding	✓ Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	✓ Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	✓ Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Gray.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.		=	APPRaised VALU

2600.3200

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House	✓ JY		32	
Misc. Bldg.	✓ JY			800 100

Total Appraised Value All Improvements \$ 4100

LAND

USE	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appra
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS	<u>5.</u>		\$ <u>400</u>					

Total Appraised Value All Lands \$ _____

Notes: R. Home Robert Deak Stone

BUILDING PERMITS

No.	Type	Date	% of Comp	Final A.

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <u>400</u>	\$ <u>40</u>
Bldgs.	\$ <u>4100</u>	\$ <u>410</u>

