



NAME Owens, Burlin & Sandra

MAP NO.: \_\_\_\_\_

X

DESCRIPTION Russell Prater 1.

DISTRICT Sandlick

MAIN BUILDING									
USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING			
Dwelling	✓ Wood Frame	✓ Wood Siding	✓ Plaster	Comp. Sh.	✓ Year Built	Bathrooms			
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms 5	Basement	✓		
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace			
Garage	Brick	C. Block	Panel	Metal	Foundation <i>Chk</i>	Stoves			
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	✓		
	Reinf. Conc.	<i>Masonry</i> ✓			Porch	Floor Fur.			
x 26 x 42 = 1092				CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE <i>21800</i>	
				SQ. FT.	<i>20 1/20 =</i>	=	=	<i>21800 17500</i>	

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$ *17000*

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1	<i>FY</i>	<i>2000/1600</i>					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes: <i>Adj Perry Owens Lot 607</i>	RECAPITULATION			
		APPRaised VALUE	ASSESSed VALUE	
	Land	\$ <i>2000 1600</i>	\$ <i>1600</i>	
	Bldgs.	\$ <i>21800 17500</i>	\$ <i>21800 17000</i>	
	TOTAL	\$ <i>23800 19100</i>	\$ <i>23400 18600</i>	