

NAME Owens, Shelby Jean
 DESCRIPTION Pratar Creek 5.

MAP NO.: _____
 DISTRICT Willis Sandlick

BLOCK _____ HOUSE NO. _____

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEAT	
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms <u>NO</u>	
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms <u>5</u>	Basement <u>NO</u>	
Service Station	Tile-C. Blk	Ash-wood shing.	Ceiled	Asbestos	No. Stories <u>1</u>	Fireplace	
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves <u>✓</u>	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	
	Reinf. Conc.		<u>Paper</u>		Porch	Floor Fur.	
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VAL
			SQ. FT.		=		<u>480</u> <u>100</u>

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House	<u>1</u>		<u>4R</u>	
Misc. Bldg.				

Total Appraised Value All Improvements \$ 1000

LAND

Lots

USE	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appr
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS			<u>\$200</u>					

Total Appraised Value All Lands \$ 300

Notes: up hollow behind Chase Owens
across P.R.

BUILDING PERMITS					
No.	Type	Date	% of Comp	Final A.	

RECAPITULATION		
	APPRAISED VALUE	ASSESSED V
Land	\$ <u>300</u>	\$ <u>30</u>
Bldgs.	\$ <u>1000</u>	\$ <u>100</u>
TOTAL	\$ <u>1300</u>	\$ <u>130</u>