

HOLBROOK BILL & JANIE
RT 1 BOX 216A
CLINTWOOD VA

24228

DATE RECORDED

DEED OR WILL BOOK

DB

CONSIDERATION

DATE RECORDED

DEED OR WILL BOOK

CONSIDERATION

DATE RECORDED

DEED OR WILL BOOK

CONSIDERATION

DATE RECORDED

DEED OR WILL BOOK

CONSIDERATION

DATE RECORDED

DEED OR WILL BOOK

CONSIDERATION

CLASS

2

ZONING

DISTRICT

02

LEGAL DESCRIPTION

REEDY RIDGE
.25AC

1992

1993

1994

1995

1996

1997

1998

1999

2000

2001

2002

2003

1,000


2,500

3,500

1,000

2,500

3,500



NOTES:

Dwelling	<input checked="" type="checkbox"/>	Comp. Sh.	<input checked="" type="checkbox"/>	Wood Siding	<input checked="" type="checkbox"/>	Yr. Built	40	Remod.		Bsmt.	<input type="checkbox"/>	2nd	<input type="checkbox"/>	Plaster		BATHS	Full	1/2 Bath(s)			
		State		Slate	<input checked="" type="checkbox"/> vinyl	No. Stories	1	1st	<input checked="" type="checkbox"/>	3rd	<input type="checkbox"/>	Sheet rock	<input checked="" type="checkbox"/>	Modern Bath	<input type="checkbox"/>	Modern Kitchen	<input type="checkbox"/>				
		Asbestos		Asb. Wood Shg.		S. Level	<input type="checkbox"/>	S. Foyer	<input type="checkbox"/>	Total No. Bedrooms		Ceiled		Cent. Heat	oil	A/C					
		Metal		Cin. Block	<input type="checkbox"/>	Stone	<input type="checkbox"/>					Panel	<input checked="" type="checkbox"/>	Flr. or Wall Furnace	<input type="checkbox"/>	Stove(s)	<input type="checkbox"/>				
Wood Frame	<input checked="" type="checkbox"/>	Tar & Grav.		Stucco	<input type="checkbox"/>	Con. Block	<input type="checkbox"/>	Crawl	<input type="checkbox"/>	Conc.	<input type="checkbox"/>	HW	<input type="checkbox"/>	Carp	<input checked="" type="checkbox"/>	Tile	<input checked="" type="checkbox"/>	Unfinished			
Cin. Block		Tile		Aluminum	<input type="checkbox"/>	Masonite	<input type="checkbox"/>	Riers	<input type="checkbox"/>	Cin. Blk.	<input checked="" type="checkbox"/>										
Steel Frame		Shakes		Storm Doors	<input type="checkbox"/>	Storm Win.	<input type="checkbox"/>	Slab	<input type="checkbox"/>	Brick	<input type="checkbox"/>	Disappearing Stairs		Gd.	<input type="checkbox"/>	Fair	<input checked="" type="checkbox"/>	Poor	<input type="checkbox"/>	VP	<input type="checkbox"/>

Basement Size	NO	Attic Floor & Stairs		Number	1														
Old	<input type="checkbox"/>	Fair	<input checked="" type="checkbox"/>	Poor	<input type="checkbox"/>	VP	<input type="checkbox"/>	Basmt. Finish		Attic	<input type="checkbox"/>	Walls	<input type="checkbox"/>	Fl.	<input type="checkbox"/>	Stone	<input type="checkbox"/>	Metal	<input type="checkbox"/>
ISFR	864	295	25488	YR.	1994	YR.		YR.											

Dwelling		D-	23591
Porch	156	6	936
Carport	House heavily damaged due to mining -		
Garage	NOT livable		
Cent. A/C	FV 2500		

Basement	M & L	M & L	Market Value All Improvements	2500		
Basmt. Finish	DATE	DATE	Market Value All Land	1000		
Attic	APRP.	APRP.	Size	Cond.		
Fireplace(s)	2000	HB	Not Home	<input type="checkbox"/>	Time	
Heating	DATE	DATE	AM	<input type="checkbox"/>	PM	<input type="checkbox"/>
Bath(s)	CLASSIFICATION	ZONING	Agric.			
Total	28424	2-2-94	Hort.			
Factor	183	2	Forest			
Replacement	23591		Open Space			
			Totals			

Public Water	<input checked="" type="checkbox"/>	Paved																		
Public Sewer		Gravel	<input checked="" type="checkbox"/>		.25				1000											
Well		Dirt																		
Spring		No Road																		
Septic System	<input checked="" type="checkbox"/>	Curb & Gutter																		
U. G. Utilities		Sidewalk			.25				1000											

General Remarks:

LEVEL SLOPES UP SLOPES DOWN

LOW STEEP UP STEEP DOWN

Land Cost	
\$	
Bldg. Cost	
\$	
Sale Price	
\$	
Rent	
\$	
Expenses	
\$	
Net Rent	
\$	

BOARD REVIEW NOTES