

NAME Roxie Wallace Church

MAP NO.: _____

DESCRIPTION West DanteDISTRICT Kenady

MAIN BUILDING													
8/30/78 7													
USE		CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING	
Dwelling		Wood Frame		Wood Siding		Plaster		Comp. Sh.		Year Built		Bathrooms	
Store		Steel Frame		Brick		Wall Board		Slate		No. Rooms		Basement	
Service Station		Flt. C. Blk	✓	Asb-wood shing.		Ceiled		Asbestos		No. Stories	1	Fireplace	
Garage		Brick		C. Block	✓	Panel		Metal	✓	Foundation	3	Stoves	
Factory		Mill		Stucco		Tile		Tar & Grav.		Floors		Cent. Heat	
Church	✓	Reinf. Conc.								Porch		Floor Fur.	
Approx x 22 x 42 = 924				CU. FT.	UNIT FACTOR		TOTAL		Physical Depreciation or Obsolescence		APPAISED VALUE		
				SQ. FT.	8		=		=		\$ 7400		

OUT BUILDINGS									
USE		CONSTRUCTION		CONDITION		SIZE		GEN. REMARKS	
Garage									
Barn									
Chicken House									
Tenant House									
Misc. Bldg.									

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	Site	FV	2000					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes: <u>L of 628</u>		RECAPITULATION		
		APPAISED VALUE		ASSESSED VALUE
	Land	\$	2000	\$
	Bldgs.	\$	7400	\$
	TOTAL	\$	9400	\$