

NAME West Dante Community Church

MAP NO.: _____

DESCRIPTION West DanteDISTRICT KENNY

MAIN BUILDING													
USE		CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING	
Dwelling		Wood Frame		✓ Wood Siding		Plaster		Comp. Sh.	✓	Year Built		Bathrooms	
Store		Steel Frame		Brick		Wall Board		Slate		No. Rooms		Basement	
Service Station		Tile-C. Blk		Asb-wood shing.		Ceiled		Asbestos		No. Stories	1	Fireplace	
Garage		Brick		C. Block		Panel		Metal		Foundation	3	Stoves	
Factory		Mill		Stucco		Tile		Tar&Grav.		Floors		Cent. Heat	
Church		Reinf. Conc.		Mas.	✓					Porch		Floor Fur.	
x 22x40 = 880		CU. FT.		UNIT FACTOR		TOTAL		Physical Depreciation or Obsolescence		APPRAISED VALUE			
		SQ. FT.		14		=		=		(R) \$ 12 300			

OUT BUILDINGS									
USE		CONSTRUCTION		CONDITION		SIZE		GEN. REMARKS	
Garage									
Barn									
Chicken House									
Tenant House									
Misc. Bldg.									

Total Appraised Value All Improvements \$

LAND				Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
		No. Acres	Value Per Acre	TOTAL				
1. Bldg. Site								
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other	Lot		EV	1000				
TOTAL				\$				

Total Appraised Value All Lands \$

Notes: <u>Rf 673</u>		RECAPITULATION		
		APPRAISED VALUE		ASSESSED VALUE
		Land	\$ 1000	\$
		Bldgs.	\$ 12300	\$
		TOTAL	\$ 13300	\$