

RECORD OF OWNERSHIP

PRES CHURCH PARSONAGE
HAYSI, VA 24256DATE
RECORDEDDEED OR
WILL BOOKCONSID-
ERATION YR-
SP

12089

DATE
RECORDEDDEED OR
WILL BOOKCONSID-
ERATIONDATE
RECORDEDDEED OR
WILL BOOKCONSID-
ERATIONDATE
RECORDEDDEED OR
WILL BOOKCONSID-
ERATIONDATE
RECORDEDDEED OR
WILL BOOKCONSID-
ERATION

BUILDING PERMITS

NO. TYPE DATE % COMP. DATE FINAL APPRAISAL APPRAISAL

NOTES:

CLASS

76

ZONING


DISTRICT

07

LEGAL DESCRIPTION

TOWN OF HAYSI
LOT

YEAR	VALUE OF LAND	VALUE OF IMPROV.	TOTAL VALUE	TAXES
1986	5000	34,400	39,400	
1987	5000	34,400	39,400	
1988	5000	34,400	39,400	
1989	5000	34,400	39,400	
1990	5000	34,400	39,400	
1991	5000	34,400	39,400	
1992				
1993				
1994				
1995				
1996				
1997				



NOTES	MAIN BUILDING	ROOFING	EXTERIOR FINISH	GENERAL FEATURES	NUMBER OF ROOMS	INTERIOR FINISH	PUMPING & HEATING
	Dwelling	Comp. Sh.	Wood Siding	Yr. Built 55 Remod.	Bsmt. [] 2nd [x]	Plaster	BATH(S) Full [x] 1/2 Bath(s) []
		Slate	Brick	No. Stories	1st [x] 3rd []	Sheet rock	Modern Bath [] Modern Kitchen []
		Asbestos	Asb. Wood Shg.	S. Level [] S. Foyer []	Total No. Bedrooms	Ceciled	Cent. Heat 7000 A/C
	CONSTRUCTION	Metal	Cin. Block [] Stone []	FOUNDATION	FLOORS	Panel	Fir. or Wall Furnace [] Stove(s) []
	Wood Frame	Tar & Grav.	Stucco [] Con. Block []	Crawl [] Conc. []	HW [] Pine [] Carp. [x] Tile []	Unfinished	FIRE PLACE(S)
	Cin. Block	Tile	Aluminum [] Masonite []	Riers [] Cin. Blk. [x]	ATTIC FINISH	INTERIOR CONDITION	Number NO
	Steel Frame	Shakes	Storm Doors [] Storm Win. []	Slab [] Brick []	Disappearing Stairs	Gd. [] Fair [x] Poor [] VP []	Number Chimneys

COMPUTATIONS				EXTERIOR CONDITION				SUMMARY OF BUILDINGS				
1/2 ² Bc	1573	28	44,044	Gd. [] Fair [x] Poor [] VP []	Basement Size 50%	Attic Floor & Stairs	INSULATION	Brick [] C. Block []	Stone [] Metal []	YR. 86	YR.	YR.

COMPUTATIONS				EXTERIOR CONDITION				SUMMARY OF BUILDINGS				
Porch	667	10	6670									
Porch												
Carport												
Garage												
Cent. A/C												
Basement	525	5	2625									
Bsmt. Finish												
Attic												
Fireplace(s)												
Heating												
Bath(s)												

COMPUTATIONS				EXTERIOR CONDITION				SUMMARY OF BUILDINGS				
Total	53,330											
Factor	.92											
Replacement	49,071											

FRONTS ON				LAND VALUE COMPUTATIONS				LAND VALUE COMPUTATIONS			
Frontage	Depth	Square Feet									

PROPERTY FACTORS				CLASSIFICATION				CLASSIFICATION			
Utilities	Street or Road			Home Site	ACRES	RATE	ADJ.	Home Site	ACRES	RATE	ADJ.
Public Water	Paved										
Public Sewer	Gravel										
Well	Dirt										
Spring	No Road										
Septic System	Curb & Gutter										
U. G. Utilities	Sidewalk										

FRONTAGE TOPOGRAPHY				General Remarks:			
LEVEL []	SLOPES UP []	SLOPES DOWN []					
LOW []	STEEP UP []	STEEP DOWN []					